



SALES and RETURN POLICY

Florida State sales tax will be charged to Florida residents and businesses when applicable. Claims of shortages or defects must be made to RENNtech within 24 hours of receipt of the merchandise. Damaged shipment claims must be made directly to the shipping carrier and are not the responsibility of RENNtech Karting.

All sales are considered final.

Prices shown online are effective 01MAY2007. Prices are subject to change without notice, due to changes in production, process, or material costs, and / or international exchange rates, at the discretion of RENNtech Karting.

All returns of unused, undamaged parts must have prior authorization from RENNtech Karting, and are subject to 15% re-stocking fee. No returns of used or damaged product will be accepted. No returns will be allowed more than 30 days after receipt of product.

RENNTECH /AIXRO XR50 WARRANTY

In general, there is no warranty on racing parts of any kind. This is a racing motor, designed for go kart racing. Only RENNtech Karting is authorized to issue warranties on XR50 engines and engine components. RENNtech Karting guarantees the faultless function of these engines when they are properly used and handled.

The buyer is obligated to document the date of purchase, correct assembly procedures, proper break-in, accurate number of operating hours, correct handling, and that appropriate steps against engine damage were taken.

Over-reving and overheating issues (running engine too lean, without water, etc.) is not covered under any circumstance. Typical signs of over-rev include separation of magneto from flywheel. Typical signs of running too lean include damage to (or failure of) rotary piston's needle bearing due to extreme temperatures.

WARRANTY PROCEDURE

In the event that a warranty claim is issued, the complete engine must be made available to RENNtech Karting. After checking the engine and determining that the cause of failure falls within the scope of warranty, damaged parts will be repaired or replaced free of charge. RENNtech Karting is not responsible or liable for shipping and handling charges, items lost or damaged during shipping, time lost, or any other damages.

The reassembly of the XR50 can be performed by RENNtech Karting's regional representative or at RENNtech Karting's location in Lake Park, FL, at the discretion of RENNtech Karting.

Please contact RENNtech Karting with any questions or concerns.

Software

Engine

Exhaust

Brakes

Suspension

Wheels

Aerodynamics

Interior

Karting